

FIG. 1




FIG. 2B ^{3/7}

W_k^N	N=4	N=8	N=16	N=32	N=64	N=128
k	1	1	1	1	1	1
						65
					33	33
						97
				17	17	17
						81
					49	49
						113
			9	9	9	9
						73
					41	41
						105
				25	25	25
						89
					57	57
						121
		5	5	5	5	5
						69
					37	37
						101
				21	21	21
						85
					53	53
						117
			13	13	13	13
						77
					45	45
						109
				29	29	29
						93
					61	61
						125

4/7

FIG. 2C

w_k^N	N=4	N=8	N=16	N=32	N=64	N=128	
k	2	2	2	2	2	2	
					66		
					34	34	
						98	
				18	18	18	
					82		
			50		50		
					114		
			10	10	10	10	
					74		
					42	42	
					106		
		26		26	26		
				90			
				58	58		
				122			
		6		6	6	6	6
						70	
						38	38
							102
			22		22	22	
					86		
				54	54		
					118		
14	14		14	14			
			78				
			46	46			
			110				
	30	30	30				
		94					
		62	62				
		126					


5/7

FIG. 2D

w_k^N	N=4	N=8	N=16	N=32	N=64	N=128
k	3	3	3	3	3	3
					67	
					35	35
						99
				19	19	
					83	
			51		51	
					115	
			11	11		
				75		
				43	43	
					107	
		27		27		
				91		
			59	59		
				123		
		7	7	7	7	
				71		
				39	39	
					103	
				23	23	
					87	
			55		55	
					119	
15	15		15			
	79					
	47		47			
			111			
	31	31				
		95				
63	63					
	127					

6/7

FIG. 3



7/7

FIG. 4